

Message

From: Shewmake, Kenneth [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=5031C1ABFE8847809A448EF4899DE65C-SHEWMAKE, KENNETH]
Sent: 2/8/2019 7:40:01 PM
To: Pereira, Stephen [pereira.stephen@epa.gov]
Subject: RE: Stephen Pereira's Comments for the Lane Plating Works Superfund Site (Sampling Analysis Plan)

Thanks
I'll get back to you if I have questions.

From: Pereira, Stephen
Sent: Friday, February 08, 2019 1:18 PM
To: Shewmake, Kenneth <shewmake.kenneth@epa.gov>
Subject: Stephen Pereira's Comments for the Lane Plating Works Superfund Site (Sampling Analysis Plan)

Greetings Kenneth,

Please see my comments for the Lane Plating Works Superfund Site Sampling Analysis Plan listed below:

1. I would like to request adding a sample location map as a part of the data summary report (Section 1.54)
2. In Section 2.34.3 the report talks about a wetland survey but it is not discussed in the phase I Remedial Investigation. The wetland survey should be performed in the contamination is confirmed in the surface water pathway (Section 2.34.3).
3. In Section 2.3.10 there is an error in the wording. The word surface water is used instead of sediment (Section 2.3.10)

Respectfully,
Stephen Pereira

Stephen Pereira REP, CESCO, CNRP, MS (Life Scientist, Remedial Project Manager)
U.S. Environmental Protection Agency (Region 6)
Superfund Division (6SF-RA)
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733

Office Telephone # (Direct) - (214) 665-3137
Work Cell Phone # - (214) 755-8616
Office Telephone # (Toll-Free) - (800) 533-3508
Office Facsimile # - (214) 665-6660 E-Mail – pereira.stephen@epa.gov

